

Standard Work #

Barracuda Cable Stripper




for 1000 MCM Aluminum (pg 1 of 2)

If there is anything wrong
(parts missing, parts not fitting properly, etc...)
Notify Your Supervisor Immediately

supv. Name
audit & training date
process owner

LEGEND: ▲ = QUALITY + = SAFETY **S** = SUCCESSIVE CHECK

VISUAL AID



step #	STEPS TO FOLLOW	FIG #
+	Always wear proper PPE: hard hat, eye protection, cut resistant gloves, hard toe boots	
1	Stripping steel insert initial set point: start with 5-40 Cap Screw head centered in the steel insert adjustment slot.	
2	Tighten 5-40 x 3/8" Cap screw with 3/32" Hex Allen Wrench	
3	To install, align slot in Barracuda Cable Stripper with Dewalt drive pin, slip on and rotate.	
4 +	If you are going to be stripping more then one conductor, tape the stripper to the barrel of the Dewalt depth gage with a couple wraps of black tape (to prevent the stripper from slipping off the barrel).	
	Enjoy many fast and ergonomic strips (10 seconds compared to 120 seconds manually)!	
	Order more strippers, anytime, when you need their assistance! asapziplines.com	
	Please provide feedback to support@asapziplines.com !	

Handwritten notes are not valid unless Supervisor / Process Tech of the area has approved them with signatures in red ink